



- [Close Window](#)
- [Print This Page](#)
- [Expand All](#) | [Collapse All](#)

## Work Order: 00012751

### Information

Work Order Number	00012751	Owner	Santos Repairs
StatusM		Priority	High
StatusT		Equip/Store	AE-10665
Status	Closed	Equip	Freezer
Parent Work Order		Model	
Account	SW Grill	S/N	4984699
Address	Street:17751 Boca Club Blvd City:Boca Raton State:FL Zipcode:33487 	Performed	3/6/2026
Tech	Israel	Invoice Number	15184
Requester	Andy Studebaker	W.O Signed by:	
WO #			

### Description

Subject	Repair TRUE REACH IN FREEZER - 17751 Boca Club Blvd
Description	*Complaint: High temperature.

### Identified and Solution

Identified

Error Message or  
Other

Solution

Other

### System Information

Created By	Santos Repairs, 3/5/2026, 3:02 PM	Last Modified By	Santos Repairs, 3/17/2026, 12:04 PM
Work Order Record Type	Print		

### Notes & Attachments

WhatsApp Image 2026-03-06 at 4.27.02 PM

Type	File
Last Modified	Santos Repairs
Description	<a href="#">Download</a>

WhatsApp Image 2026-03-06 at 4.27.02 PM (1)

Type	File
Last Modified	Santos Repairs
Description	<a href="#">Download</a>

### Files

**WhatsApp Image 2026-03-06 at 4.27.02 PM**

Last Modified **3/17/2026, 12:03 PM**

Created By **Santos Repairs**

**WhatsApp Image 2026-03-06 at 4.27.02 PM (1)**

Last Modified **3/17/2026, 12:03 PM**

Created By **Santos Repairs**